CONTROL MAR 3 1 1992

_	EPIDEMIOLOGIC NVESTIGATION 100 Was initiated by a consumer's complaint 100 was initiated by a consumer's complaint 100 er oven iginited a piece of bread she was					
toasting in the unit on 2-20-92. Wi	in approximately one minute of beginning the					
toasting process, the bread charred and caught fire, requiring the consumer to put out the flames with a fire extinguisher. No injuries resulted from this						
incident.						
7. LOCATON (Marma, scrool erg.) kitchen of home	e crry Milwaukee WI WI WI I					
toaster oven 11A TRADE/BRAND NAME, MODEL NUMBER: TRO40_TY2-model MANUFACTURER 1 ADDRESS Black and Decker (U.S.) Inc., Shelton, CT.						
· · · · · · · · · · · · · · · · · · ·	FACTURER & ADDRESS A					
12. AGE OF VICTIM 9 9 9 9 MALE -1 FEMALE -2 UNKNOWN -3	DISPOSITION 15. INJURY DIAGNOSIS No injury 0 No injury 7 1					
No injury 9 9 Complainant	Friend) 18. TYPE INVESTIGATION 19. TIME SPENT TY: 1.0 O SITE 1 TELEPHONE 2 1 OTHER 3					
Multiple 9 Consumer complain	22. REVIEWED BY YR MO DAY 0 7 8 1 3 0 9:20325					
ZZL PERMISSION TO DISCLOSE NAMES .						
(NON-NEISS CASES ONLY) CPSC MAY DISCL	E MY NAME X CPSC MAY NOT DISCLOSE MY NAME					
24. NARRATIVE (See Instructions on Other Scientific See attached narrative.	25. REGIONAL OFFICE DIRECTOR REVIEW DATE					
MFR/FRVLER STIFIED The Country The Country	made maned mans tropasted					
(USE OTHER SIL	and additional sheets if necessary)					

* THROUGH 5/31/94 ONR NO. 3041-0029

CONTITUMAR 3 1 1992 7/.

1. CASE NO.	2. INVESTIGATOR'S ID	1. OFFICE COD	E	EPIDEMIO	i ngic		
920303CCN1236	9 0 0 3 8 3 0			INVESTIGATION			
4 DATE OF YR MO DAY ACCIDENT 9 2 0 2 2 0	5. DATE INVESTIGATION INITIATED	9 2 0 3	0 9	REPOR	1		
8. SYNOPSIS OF ACCIDENT OR COMPLAINT This investigation was initiated by a consumer's complaint							
that her Black and Decker brand toaster oven iginited a piece of bread she was toasting in the unit on 2-20-92. Within approximately one minute of beginning the							
toasting process the br		•					
put out the flames with		_		_			
incident.							
7. LOCATION (Home, school, etc.)		a. CITY		9. STATE			
kitchen of home	1 0	Milwaukee		WI	WI		
104 FIRST PRODUCT 114 TRADE/BRAND NAME, MODEL NUMBER: TRO40_TY2-Model MANUFACTURER & ADDRESS							
toaster oven 0 2 1 6 Black and Decker (U.S.) Inc., Shelton, CT.							
108. SECONO PRODUCT	MAN MAN	DEBRAND NAME, MODEL IUFACTURER & ADDRESS	NUMBER,				
N/A 0 0		i/A	·				
9 9 9 FEMALE	1-2 9 1-3	No injury	0	No injury	7 1		
16. BCDY PART	7. RESPONDENT(S) (Morne	r, Fnend)	18. TYPE INVEST	IGATION 19. TI	ME SPENT Tr:1.		
No injury 9 9	Complainant	1	TELEPHONE OTHER	2 1	0 4 0		
20. ATTACHMENTS	21. CASE SOURCE	2	2. REVIEWED BY	YR N	O DAY		
Multiple 9	Consumer complaint	0 7	8 1 3	0 920	325		
23. PERMISSION TO DISCLOSE NAMES	-	X					
INON-NEISS CASES ONLY)	CPSC MAY DISCLO	SE MY NAME	CPSC A	MAY NOT DISCLOSE MY NAM	E		
24. NARRATIVE (See Instructions on Other Side)		-	S. REGIONAL OFFICE	DIRECTOR REVIEW	DATE		
See attached narrative	•						
					!		
			•				
					•		
	-			14			
Ş.	(USE OTHER SIDE AND ADDITIONAL SHEETS IF NECESSARY)						

CPSC FORM NO. 182 (Revised 10/85)



THROUGH 5/31/94 CMR NO. 3041-0029

SUMMARY:

This investigation was initiated by a consumer's complaint that her Black & Decker toaster oven ignited a piece of bread she was toasting in the unit on 2/20/92.

Within approximately one minute of starting the toaster, the bread was charred and caught fire, requiring the complainant to put out the fire with a fire extinguisher. No injuries resulted from this incident.

PRE-INCIDENT:

The complainant purchased a Black & Decker TRO40 "Toast-R-Oven" from a Kohl's Department Store located at 5300 S. 76th St., in Greendale, WI in approximately spring of 1989. This unit was purchased new at a cost of approximately \$45. The toaster oven has been used on a daily basis since being purchased, and has worked properly.

The complainant read the operating instructions when first purchasing the unit, and stated that she has referred to them periodically since that time. She expressed familiarity with the safety precautions printed on pages 2 and 3 of the instruction booklet, which is attached to this report as Exhibit "A."

The toaster oven was kept on the kitchen counter; no extension cord was used, and the appliance's approximately 3 foot cord was lying loosely on top of the counter. The unit was plugged into a standard three prong household electrical outlet.

INCIDENT:

At approximately noon on 2/20/92 the complainant put a single piece of standard sized bread on the crumb food rack in the toaster. The toast color selector was set at approximately 3/4 of its full range, the same setting it has been set on for years. The bake/broil temperature control was turned to the off position.

After approximately one minute, the complainant noted that the bread slice had started on fire inside the toaster. She immediately opened the toaster oven access door, and extinguished the open flames with a fire extinguisher. The slice of bread was found to be completely charred, however the toaster oven did not appear to have suffered any significant damage. The toaster should have turned off automatically at the settings described above, without burning the bread.

POST INCIDENT:

Complainant called a local Black & Decker (U.S.), Incorporated Household Appliance Authorized Service Center, located at 10424 W., Bluemound Rd., in Brookfield, WI, (414) 453-4240 to complain about the product. The complainant was told to bring in the toaster, and advised that sne would be reimbursed for the cost of a similar replacement toaster oven, up to a \$60 value. The complainant intends to return the unit to Black & Decker for the agreed upon refund, and did not wish to turn the toaster oven over to the CPSC as requested.

On 3/9/92 this investigator viewed the toaster oven at the complainant's residence. The toaster oven is described as a model TRO40-TY2 tan and black in color, 120 volt, 1500 watts, 50-60Hz. There is a further marking on the bottom of the unit noting "UL listed, 228E," and a warning "disconnect toaster before cleaning." The appliance appears to be in generally good condition, and appeared to be generally clean and free from crumbs. The crumb tray was not warped or loose fitting, and the heating elements appeared to be straight and not sagging.

Photographs were taken of the toaster oven, and are included with this report as Exhibit "B." The toaster oven was not collected as a sample, due to the complainant's wish to return the item to the manufacturer for a refund.

The complainant signed an "Authorization For Release of Name" form allowing disclosure of her name if necessary; this form is attached to this report as Exhibit "C."

PRODUCT IDENTIFICATION:

MANUFACTURER: Black & Decker (U.S.), Inc.

6 Armstrong Rd. Shelton, CT 06484

MODEL: TRO40-TY2 "Toast-R-Oven"

DESCRIPTION: Black and tan in color, 120 volts, 1500 watts,

50-60 Hz; purchased new in spring 1989.

RETAILER: Kohl's Department Store

5300 S. 76th St. Greendale, WI


LOCAL SERVICE CENTER: Black & Decker (U.S.), Inc.

10424 W. Bluemound Rd.


Brookfield, WI (414) 453-4240

ATTACHMENTS:

- Attachment A Instruction booklet complainant received with the appliance with purchasing the unit new in spring 1989.
- Attachment B Photographs of toaster oven involved in this incident.
- Attachment C "Authorization For Release of Name" form dated 3/9/92.
- Attachment D Copy of original consumer product incident report.




Photos of Black and Decker Model TRO40 toaster oven.




IDI# 920303CCN1236


Exhibit "B"




Above: Interior of toaster oven; Below: labeling on back of unit.



IDI# 920303CCN1236




Above: Labeling identifying model number. Below: Warning labeling on crumb tray.





BLACK & DECKER®

Toast-R-Oven™ Broilers



Series TRO30 through TRO60's

1500 Watts, 120 Volts, 50/60 Hz, AC Only Listed by Underwriters Laboratories, Inc.

Every Black & Decker product is of the highest quality. If you have any questions concerning the use of your Toast-R-Oven, please call us-**TOLL FREE**-from 8:00 a.m. to 5:00 p.m. Eastern Time, Monday thru Friday at:

TOLL FREE# - 800-421-8668

(NORTH CAROLINA residents only)
TOLL FREE# — 800-222-2839

SAVETHIS USE & CAREBOOK

Exhibit "D"

CONSUMER PRODUCT INCIDENT REPORT

1. NAME OF RESPONDEN	п	2. TELSPI	HONE NO. (Ham	e) (Work)		
Susan Stickel	.s	Ног	ne: 414-332 - 128	8 Work: 414-423-7721		
3. STREET ADDRESS	and Avenue	4. CITY	4. CITY STATE ZIP CCCE			
4401 N. Maryland Avenue Milwaukee, WI. 53211 Milwauke				3211		
S. DESCRIBE ACCIDENT SITUATION OR HAZARD, INCLUDING DATA ON INJURIES. (Use second page if necessary.)						
Withing appro	espondent was making toast in eximately one minute, the tobe respondent to put out the	aster ca	aused the bread	l to start on fire,		
6. DATE OF INCIDENT(S)	7. IF INJURY OR NEAR MISS, OBTAIN AGE SEX AND DI INJURY No _injury	ESCRIBE	NAME N/A	FROM RESPONDENT, PROVIDE		
A DESCRIPTION OF REC			10. BRAND NAME			
toaster oven			"Black and Decker"			
11. MANUFACTURER/DIS	TRIBUTOR NAME, ADDRESS & PHONE		12. MODEL, SERIAL NO.'S			
10424 W. Bluemound Road Brookfield, WI. ph.# 414-453-4240 Tousan. Md.		13. DEALER'S NAME, ADDRESS & PHONE Kohl's Department Store 5300 S76th Street Greendale, WI.				
14. WAS THE PRODUCT DAMAGED, REPAIRED OR MODIFIED? YES NO _XX IF YES, BEFORE OR AFTER THE			15. PRODUCT PURCHASED NEW USED DATE PURCHASED 1989 AGE			
Describe			16. DOES PRODUCT HAVE WARNING LABELS? IF SO, NOTE:unknown			
17. HAVE YOU CONTACTED THE MANUFACTURER? YES XX NO IF NOT, DO YOU PLAN TO YES XX CONTACT THEM? OTHER offered to replace item.			19. MAY WE USE YOUR NAME WITH THIS REPORT? YES XX NO			
20. DATE RECEIVED	FOR AI	DMINISTRA	TION USE	22. DOCUMENT NO.		
2-26-92	Definis R. B		MKE/RP	G223_0313		
Investigation 920303 CCN 1236			24. PRODUCT CODE(S)			
FOCR, EPD	s, foer	28. END	CRSER'S NAME & TITLE	Regional Director		